
This drawing, specifications, and concepts contained here in are the sole property of Dart Aerospace, and may not be reproduced or used in any fashion without the prior written permission of Dart Aerospace Eugene, OR.


REVISIONS									
REV	ECR	DESCRIPTION	DATE	INITIAL	APPROVED				
3		AS DRAWN BY CANAM.	7/22/2013	CFS					
4	15-0355	updated to new drafting standards. Added flat pattern. Ch'd dim was (.250) is .25.	11/13/2015	DPD	JAG				

SEE ATTACHED DEVIATION



USED ON

20NR-119 8NR-119 20NR-86 8NR-86





Description

BRACKET

Material

A36





ASSY QTY

B/O

20NR-119-1

DWG NO.	20NF	R-119-1		REV 4		
MAT'L A36		DRAWN BY:	CANAM			
	HERWISE SPECIFIED	APPROVED	D Weil	2		
.xxx ± .010	FRACTIONS ± 1/8 ANGLES ±1°	HEAT TREAT				
.XX ± .03		FINISH SEE WELDMENT				
1. BREAK ALL SHARP EDGES .015 x 45° SPEC						
OR .015R	IMITS APPLY AFTER	USED ON MODEL				
PLATING						
SCALE 4.0	DATE 11	/4E/400E	CLIEFT 4 OF	- 1		

BRACKET

B/O INFORMATION OR SPECIFICATIONS

11/15/1995 SHEET 1 OF 1

Entered:Date:				ANDT	
	AFROSPACE				
NCR No.		FORMANCE / ROUTE UPDATE Route update only			
t a la	DISPOSITION	DEPARTMENT/PROCESS			
Job:					
Part No. 20h /8 - 119 - 1	Rework	Skid-tube Cross tube Machining Small Fab	Eng. (Non-AW)	Engineering Water Jet	
Part No. 20 VR - 119 - 1	Scrap	1	Prod. Eng. Coor. Rec/Store/Packaging		
REV 4	Use-as-is	Large Fab Finishing	Rec/Store/Packaging	Quality	
Date: 1(100 100)	Seguence #:	QTY Affected :		MRB (Q\$(042)	
Date: 4/29/2019	ocquence n.	QTT / Medica :		\ XX	
Description Wor	k Order Deviation	Disposition		V' (
		•		Completed By	
DIMENSION 5.589	ON FLAT PATTERN	-THIS DEVIATION IS A	ACCEPTABLE TO	Completed by	
CHANGED FOR 5.8		USE			
CHANGED FOR 3.0				Lead hand / Supervisor	
		- FIT FORM AND FUI			
		BE AS ORIGINALL			
		DE 110 ONIGHT OF CE			
				QC / QA Coordinator	
Root Cause		FAULT CATEGORY			
· · · · · · · · · · · · · · · · · · ·	Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong	
Operator	Bending	Misaligned/off center	Folio/Program	Outside Tolerance	
Manufacturing Process	Crushing	BOM/Route	Grain Direction	Drawing	
Equip/Tooling	Cracks	Broken/Damage/Defect	Weld	Finish	
Handling/Presservation	Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing	
Material	Marks/Chatter	Drill Holes	Out of Sequence	Misread	
Product Improvement	Mislabeled	Fit/Function	Off-set/Set-up		
Process Improvement	Other/Details:				
Human Factors					